

Technical Specifications

| Temperature Conversion Table | | | | | | | |
|---|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| Conversion Formulas | | | | | | | |
| $^{\circ}\text{F} = (9/5 \times ^{\circ}\text{C}) + 32^{\circ}$ | | | | | | | |
| $^{\circ}\text{C} = 5/9 (^{\circ}\text{F} - 32^{\circ})$ | | | | | | | |
| $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ |
| 600 | 316 | 1000 | 538 | 1400 | 760 | 1800 | 982 |
| 610 | 321 | 1010 | 543 | 1410 | 766 | 1810 | 988 |
| 620 | 327 | 1020 | 549 | 1420 | 771 | 1820 | 993 |
| 630 | 332 | 1030 | 554 | 1430 | 777 | 1830 | 999 |
| 640 | 338 | 1040 | 560 | 1440 | 782 | 1840 | 1004 |
| 650 | 343 | 1050 | 566 | 1450 | 788 | 1850 | 1010 |
| 660 | 349 | 1060 | 571 | 1460 | 793 | 1860 | 1016 |
| 670 | 354 | 1070 | 577 | 1470 | 799 | 1870 | 1021 |
| 680 | 360 | 1080 | 582 | 1480 | 804 | 1880 | 1027 |
| 690 | 366 | 1090 | 588 | 1490 | 810 | 1890 | 1032 |
| 700 | 371 | 1100 | 593 | 1500 | 816 | 1900 | 1038 |
| 710 | 377 | 1110 | 599 | 1510 | 821 | 1910 | 1043 |
| 720 | 382 | 1120 | 604 | 1520 | 827 | 1920 | 1049 |
| 730 | 388 | 1130 | 610 | 1530 | 832 | 1930 | 1054 |
| 740 | 393 | 1140 | 616 | 1540 | 838 | 1940 | 1060 |
| 750 | 399 | 1150 | 621 | 1550 | 843 | 1950 | 1066 |
| 760 | 404 | 1160 | 627 | 1560 | 849 | 1960 | 1071 |
| 770 | 410 | 1170 | 632 | 1570 | 854 | 1970 | 1077 |
| 780 | 416 | 1180 | 638 | 1580 | 860 | 1980 | 1082 |
| 790 | 421 | 1190 | 643 | 1590 | 866 | 1990 | 1088 |
| 800 | 427 | 1200 | 649 | 1600 | 871 | 2000 | 1093 |
| 810 | 432 | 1210 | 654 | 1610 | 877 | 2010 | 1099 |
| 820 | 438 | 1220 | 660 | 1620 | 882 | 2020 | 1104 |
| 830 | 443 | 1230 | 666 | 1630 | 888 | 2030 | 1110 |
| 840 | 449 | 1240 | 671 | 1640 | 893 | 2040 | 1116 |
| 850 | 454 | 1250 | 677 | 1650 | 899 | 2050 | 1121 |

Technical Specifications

| Temperature Conversion Table | | | | | | | |
|---|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| Conversion Formulas | | | | | | | |
| $^{\circ}\text{F} = (9/5 \times ^{\circ}\text{C}) + 32^{\circ}$ | | | | | | | |
| $^{\circ}\text{C} = 5/9 (^{\circ}\text{F} - 32^{\circ})$ | | | | | | | |
| | | | | | | | |
| $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ | $^{\circ}\text{F}$ | $^{\circ}\text{C}$ |
| 2060 | 1127 | 2070 | 1132 | 2080 | 1138 | 2090 | 1143 |
| 2100 | 1149 | 2110 | 1154 | 2120 | 1160 | 2130 | 1166 |

stern-leach

49 Pearl Street

Attleboro, MA 02703

T: 1-508-222-7400 F: 1-508-699-4030